

Lead Sample Test Results and Actions

LINCOLN ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 001	Room 1A	Yes		Fixture permanently removed		
FX 002	sink room 1A	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required
FX 003	Restroom 1A	Yes				
FX 004	Restroom 1A	Yes				
FX 005	Room 2A	Yes		Fixture permanently removed		
FX 006	sink room 2A	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required
FX 007	Restroom 2A	Yes				
FX 008	Restroom 2A	Yes				
FX 009	Room 3A	Yes		Fixture permanently removed		
FX 010	sink room 3A	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required
FX 011	Restroom 3A	Yes				
FX 012	Restroom 3A	Yes				
FX 013	Room 4A	Yes		Fixture permanently removed		
FX 014	sink room 4A	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required
FX 015	Restroom 4A	Yes				
FX 016	Restroom 4A	Yes				
FX 017	Custodian closet	Yes				
FX 018	Room 1	Yes		Fixture permanently removed		
FX 019	sink room 1	Yes	0.001			Re-tested after adding filter 12/6/2022; No further action required
FX 020	Restroom #1	Yes				
FX 021	Room 2	Yes		Fixture permanently removed		

Lead Sample Test Results and Actions

LINCOLN ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.	
FX 022	sink room 2	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 023	Restroom # 2	Yes					
FX 024	Room 3	Yes	Fixture permanently removed				
FX 025	sink room 3	Yes	0.001			Re-tested after adding filter 12/6/2022; No further action required	
FX 026	Restroom #3	Yes					
FX 027	Room 4	Yes	Fixture permanently removed				
FX 028	sink room 4	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 029	Restroom #4	Yes					
FX 030	Room 5	Yes	Fixture permanently removed				
FX 031	sink room 5	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 032	Restroom #5	Yes					
FX 033	Room 6	Yes	Fixture permanently removed				
FX 034	sink room 6	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 035	Restroom #6	Yes					
FX 036	Boiler Room	Yes					
FX 037	Kitchen sprayer sink	Yes	0.002			Re-tested; Passed 10/8/21; No further action required	
FX 038	Kitchen sink	Yes	0.0009			Re-tested; Passed 10/8/21; No further action required	
FX 039	Kitchen sink	Yes	0.001			Re-tested; Passed 10/8/21; No further action required	
FX 040	Kitchen custodial sink	Yes	0.001			Re-tested; Passed 10/8/21; No further action required	

Lead Sample Test Results and Actions

LINCOLN ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.	
FX 041	Kitchen custodial sink	Yes	0.001			Re-tested; Passed 10/8/21; No further action required	
FX 042	Aides	Yes					
FX 043	Main Office	Yes					
FX 044	Principal Office	Yes					
FX 045	sink PTA room	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 046	Library sink	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 047	Outside restroom	Yes	0.003			No action	
FX 048	Outside restroom	Yes	0.002			No action	
FX 049	Outside restroom	Yes	Fixture permanently removed				
FX 050	Outside restroom	Yes	Fixture permanently removed				
FX 051	Custodian closet	Yes					
FX 052	Girls restroom	Yes					
FX 053	Girls restroom	Yes					
FX 054	Girls restroom	Yes					
FX 055	Girls restroom	Yes					
FX 056	Boys restroom	Yes					
FX 057	Boys restroom	Yes					
FX 058	Boys restroom	Yes					
FX 059	Engineer's Office	Yes					
FX 060	sink room 7	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 061	sink room 9	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 062	#9	Yes	Fixture permanently removed				

Lead Sample Test Results and Actions

LINCOLN ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.	
FX 063	sink room 10	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 064	#10	Yes	Fixture permanently removed				
FX 065	sink room 11	Yes	0.001			Re-tested after adding filter 12/6/2022; No further action required	
FX 066	#11	Yes	Fixture permanently removed				
FX 067	sink room 12	Yes	0.001			Re-tested after adding filter 12/6/2022; No further action required	
FX 068	#12	Yes	Fixture permanently removed				
FX 069	sink room 13	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 070	sink room 14	Yes	0.001			Re-tested after adding filter 12/6/2022; No further action required	
FX 071	#14	Yes					
FX 072	sink room 16	Yes	0.0009			Re-tested after adding filter 12/6/2022; No further action required	
FX 073	#15	Yes	Fixture permanently removed				
FX 074	sink room 15	Yes	0.002			Re-tested after adding filter 12/6/2022; No further action required	
FX 075	Between Rm 15, 16	Yes	0.0009			No action	
FX 076	Between Rm 15, 16	Yes	0.0009			No action	
FX 077	Between Rm 15, 16	Yes	0.0009			No action	
FX 078	Outside	Yes					
FX 079	Outside	Yes					
FX 080	Outside	Yes					
FX 081	Outside	Yes					
FX 082	Outside	Yes					
FX 083	Outside	Yes					

Lead Sample Test Results and Actions

LINCOLN ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 084	Outside	Yes				
FX 085	Outside	Yes				
FX 086	Outside	Yes				
FX 087	Outside	Yes				
FX 088	Outside	Yes				
FX 089	Outside	Yes				
FX 090	Outside	Yes				
FX 091	Outside	Yes				
FX 092	Custodian closet in kitchen	Yes				