

Lead Sample Test Results and Actions

EAST MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 001		No				
FX 002		No				
FX 003		No				
FX 004	Engineer office sink	Yes	0.0009			No action required
FX 005		No				
FX 006		No				
FX 007		No				
FX 008	Kitchen hand sink	Yes	0.003			No action required
FX 009	Kitchen dish sprayer	Yes	0.002			No action required
FX 010	Kitchen sink	Yes	0.0009			No action required
FX 011	Kitchen sink	Yes	0.0009			No action required
FX 012	Kitchen pot filler	Yes	0.001			No action required
FX 013	Kitchen pot filler	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 014	Kitchen pot filler	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 015	Kitchen pot filler	Yes	0.003			No action required
FX 016		No				
FX 017		No				
FX 018		No				
FX 019		No				
FX 020		No				
FX 021		No				
FX 022		No				
FX 023		No				
FX 024		No				
FX 025	A wing hall fount.	Yes	0.003			No action required
FX 026	Room A3 sink	Yes	0.004			No action required
FX 027		No				
FX 028		No				
FX 029		No				
FX 030		No				

Lead Sample Test Results and Actions

EAST MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 031		No				
FX 032		No				
FX 033		No				
FX 034		No				
FX 035	Kitchen sink B1 C/A	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 036	Kitchen sink B1 C/A	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 037	Kitchen sink B1 C/A	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 038	Kitchen sink B1 C/A	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 039	Kitchen sink B1 C/A	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 040	Kitchen sink B1 C/A	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 041		No				
FX 042		No				
FX 043		No				
FX 044		No				
FX 045		No				
FX 046		No				
FX 047		No				
FX 048		No				
FX 049		No				
FX 050	Hi fount. B wing hall	Yes	0.002			No action required
FX 051	Lo fount. B wing hall	Yes	0.002			No action required
FX 052		No				
FX 053		No				
FX 054		No				
FX 055		No				
FX 056		No				
FX 057		No				

Lead Sample Test Results and Actions

EAST MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 058		No				
FX 059		No				
FX 060		No				
FX 061		No				
FX 062		No				
FX 063		No				
FX 064		No				
FX 065		No				
FX 066		No				
FX 067		No				
FX 068	Hi fount. west gym	Yes	0.001			No action required
FX 069	Lo fount. west gym	Yes	0.001			No action required
FX 070	Hi fount. east gym	Yes	0.0009			No action required
FX 071	Lo fount. east gym	Yes	0.0009			No action required
FX 072	Bottle filler east gym	Yes	0.0009			No action required
FX 073		No				
FX 074		No				
FX 075		No				
FX 076	Fount. girls locker rm	Yes	0.004			No action required
FX 077		No				
FX 078		No				
FX 079		No				
FX 080		No				
FX 081		No				
FX 082		No				
FX 083		No				
FX 084		No				
FX 085		No				
FX 086		No				
FX 087		No				
FX 088		No				
FX 089		No				

Lead Sample Test Results and Actions

EAST MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 090		No				
FX 091		No				
FX 092		No				
FX 093		No				
FX 094		No				
FX 095	Hi fount. gym hall W	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 096	Lo fount. gym hall W	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 097	Fountain gym hall W.	Yes	0.004			No action required
FX 098		No				
FX 099		No				
FX 100		No				
FX 101		No				
FX 102		No				
FX 103		No				
FX 104		No				
FX 105		No				
FX 106		No				
FX 107	Bottle filler office hall	Yes	0.0009			No action required
FX 108	Lo fount. office hall	Yes	0.0009			No action required
FX 109	Hi fountain office hall	Yes	0.0009			No action required
FX 110		No				
FX 111		No				
FX 112		No				
FX 113		No				
FX 114		No				
FX 115	Room G18 sink	Yes	0.002			No action required
FX 116		No				
FX 117		No				
FX 118		No				
FX 119		No				
FX 120	D wing fountain	Yes	0.0009			No action required

Lead Sample Test Results and Actions

EAST MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 121	Room G7 sink	Yes	0.0009			Re-tested after adding filter 1/4/2022; No further action required
FX 122		No				
FX 123		No				
FX 124		No				
FX 125		No				
FX 126		No				
FX 127		No				
FX 128		No				
FX 129		No				
FX 130		No				
FX 131	Room G10 sink	Yes	0.003			No action required
FX 132		No				
FX 133		No				
FX 134		No				
FX 135		No				
FX 136		No				
FX 137		No				
FX 138		No				
FX 139		No				
FX 140		No				
FX 141	G wing hi fountain	Yes	0.001			No action required
FX 142	G wing low fountain	Yes	0.001			No action required
FX 143	G wing fountain	Yes	0.0009			No action required
FX 144	G wing bottle filler	Yes	0.0009			No action required
FX 145		No				
FX 146	Room H6 sink	Yes	0.001			No action required
FX 147		No				
FX 148		No				
FX 149	Room H9 sink	Yes	0.001			No action required
FX 150		No				
FX 151		No				

Lead Sample Test Results and Actions

EAST MIDDLE SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 152		No				
FX 153		No				
FX 154		No				
FX 155		No				
FX 156		No				
FX 157		No				
FX 158		No				
FX 159		No				
FX 160		No				
FX 161		No				
FX 162		No				
FX 163		No				
FX 164		No				
FX 165		No				
FX 166		No				
FX 167		No				
FX 168	H wing hi fountain	Yes	0.0009			No action required
FX 169	H wing low fountain	Yes	0.0009			No action required
FX 170	H wing fountain	Yes	0.0009			No action required
FX 171	H wing bottle filler	Yes	0.0009			No action required