

Lead Sample Test Results and Actions

MORNINGSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 001		No				
FX 002	Rm A1 fountain	Yes	0.002			No action
FX 003		No				
FX 004	Rm A2 fountain	Yes	0.002			No action
FX 005		No				
FX 006	Rm K1 fountain	Yes	0.0009			No action
FX 007		No				
FX 008	Rm K2 fountain	Yes	0.0009			No action
FX 009	Rm A6 fountain	Yes	0.0009			No action
FX 010		No				
FX 011		No				
FX 012	Rm A5 fountain	Yes	0.0009			No action
FX 013		No				
FX 014	Rm A4 fountain	Yes	0.001			No action
FX 015		No				
FX 016	Rm A3 fountain	Yes	0.004			No action
FX 017		No				
FX 018		No				
FX 019		No				
FX 020		No				
FX 021	A wing fountain high	Yes	0.0009			No action
FX 022	A wing fountain low	Yes	0.0009			No action
FX 023	A wing bottle filler	Yes	0.0009			No action
FX 024		No				
FX 025		No				
FX 026		No				
FX 027	Computer lab fountain	Yes	0.003			No action
FX 028		No				
FX 029	Rm B2 fountain	Yes	0.005		Must be fixed, replaced or removed	
FX 030		No				
FX 031	Rm B3 fountain	Yes	0.002			No action
FX 032		No				
FX 033	Rm B4 fountain	Yes	0.002			No action
FX 034		No				
FX 035	Rm B5 fountain	Yes	0.001			No action

Lead Sample Test Results and Actions

MORNINGSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 036		No				
FX 037	Rm B6 fountain	Yes	0.003			No action
FX 038		No				
FX 039		No				
FX 040		No				
FX 041	B wing fountain right	Yes	0.003			No action
FX 042	B wing fountain left	Yes	0.003			No action
FX 043		No				
FX 044		No				
FX 045		No				
FX 046		No				
FX 047	Library fountain	Yes	0.003			No action
FX 048	Rm C1 sink	Yes	0.0009			No action
FX 049		No				
FX 050		No				
FX 051		No				
FX 052	Rm C2 fountain	Yes	0.001			No action
FX 053		No				
FX 054	Rm C3 fountain	Yes	0.003			No action
FX 055		No				
FX 056	Rm C4 fountain	Yes	0.001			No action
FX 057		No				
FX 058	Rm C5 fountain	Yes	0.001			No action
FX 059		No				
FX 060	Rm C6 fountain	Yes	0.002			No action
FX 061		No				
FX 062		No				
FX 063		No				
FX 064	C wing fountain	Yes	0.0009			No action
FX 065	C wing bottle filler	Yes	0.0009			No action
FX 066		No				
FX 067		No				
FX 068		No				
FX 069		No				
FX 070	Café fountain high	Yes	0.0009			No action

Lead Sample Test Results and Actions

MORNINGSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 071	Café fountain low	Yes	0.004			No action
FX 072	Kitchen sprayer	Yes	0.001			No action
FX 073	Kitchen sprayer	Yes	0.0009			No action
FX 074	Kitchen faucet	Yes	0.0009			No action
FX 075	Kitchen faucet	Yes	0.0009			No action