

Lead Sample Test Results and Actions

RIVERVIEW ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 001		No				
FX 002		No				
FX 003		No				
FX 004		No				
FX 005		No				
FX 006		No				
FX 007		No				
FX 008		No				
FX 009		No				
FX 010	Kitchen sink west wall	Yes	0.0009			No action required
FX 011	Kitchen sprayer S wall	Yes	0.0009			No action required
FX 012		No				
FX 013	Cafeteria fountain	Yes	0.0009			No action required
FX 014	Fountain West Hall low	Yes	0.0009			No action required
FX 015		No				
FX 016		No				
FX 017		No				
FX 018		No				
FX 019	Room K1 fountain	Yes	0.002			No action required
FX 020		No				
FX 021		No				
FX 022		No				
FX 023	Room K2 fountain	Yes	0.003			No action required
FX 024		No				
FX 025		No				
FX 026		No				
FX 027		No				
FX 028		No				
FX 029	Room A1 fountain	Yes	0.001			No action required
FX 030		No				
FX 031	Room A2 fountain	Yes	0.001			No action required
FX 032		No				
FX 033	Room A3 fountain	Yes	0.0009			No action required
FX 034		No				
FX 035	Room A4 fountain	Yes	0.001			No action required
FX 036		No				

Lead Sample Test Results and Actions

RIVERVIEW ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 037	Room A5 fountain	Yes	0.0009			No action required
FX 038		No				
FX 039	Room A6 fountain	Yes	0.001			No action required
FX 040		No				
FX 041	Room B1 fountain	Yes	0.001			No action required
FX 042		No				
FX 043	Room B2 fountain	Yes	0.0009			No action required
FX 044		No				
FX 045	Room B3 fountain	Yes	0.001			No action required
FX 046		No				
FX 047	Room B4 fountain	Yes	0.0009			No action required
FX 048		No				
FX 049	Room B5 fountain	Yes	0.001			No action required
FX 050		No				
FX 051	Room B6 fountain	Yes	0.001			No action required
FX 052		No				
FX 053	Room C1 fountain	Yes	0.001			No action required
FX 054		No				
FX 055	Room C2 fountain	Yes	0.001			No action required
FX 056		No				
FX 057	Room C3 fountain	Yes	0.002			No action required
FX 058		No				
FX 059	Room C4 fountain	Yes	0.0009			No action required
FX 060		No				
FX 061	Room C5 fountain	Yes	0.0009			No action required
FX 062		No				
FX 063	Room C6 fountain	Yes	0.001			No action required
FX 064		No				
FX 065		No				
FX 066		No				
FX 067	High fountain by Boys	Yes	0.002			No action required
FX 068	Low fountain by Boys	Yes	0.002			No action required
FX 069		No				
FX 070	Low fountain by Girls	Yes	0.0009			No action required
FX 070A	Bottle filler by Girls	Yes	0.0009			No action required
FX 071	High fountain by Girls	Yes	0.0009			No action required
FX 072		No				

Lead Sample Test Results and Actions

RIVERVIEW ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 073	Bottle filler C4 wing	Yes	0.0009			No action required
FX 074	High fountain C4 wing	Yes	0.0009			No action required
FX 075	Low fountain C4 wing	Yes	0.0009			No action required