

Lead Sample Test Results and Actions

SUNNYSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 001		No				
FX 002	Room C1 fountain	Yes	0.003			No action required
FX 003	Room C2 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 004	Room C2 fountain	Yes	0.005		Removed	
FX 005	Room C3 sink	Yes	0.002			Re-tested after adding filter 1/13/2022; No further action required
FX 006	Room C3 fountain	Yes	0.009		Removed	
FX 007		No				
FX 008	Room C4 fountain	Yes	0.003			No action required
FX 009	Room C5 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 010	Room C5 fountain	Yes	0.007		Removed	
FX 011	Room C6 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 012	Room C6 fountain	Yes	0.006		Removed	
FX 013		No				
FX 014	Room A1 fountain	Yes	0.003			No action required
FX 015	Room A2 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 016	Room A2 fountain	Yes	0.007		Removed	
FX 017		No				
FX 018	Room A3 fountain	Yes	0.004			No action required
FX 019		No				
FX 020	Room K1 fountain	Yes	0.003			No action required
FX 021		No				
FX 022	Room A4 fountain	Yes	0.002			No action required
FX 023		No				
FX 024	Room A5 fountain	Yes	0.002			No action required
FX 025	Room A6 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 026	Room A6 fountain	Yes	0.081	Immediately removed from service		
FX 027	Room K2 sink	Yes	0.004			No action required
FX 028		No				
FX 029	Room B1 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 030	Room B1 fountain	Yes	0.005		Removed	

Lead Sample Test Results and Actions

SUNNYSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 µg/L less than 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 031	Room B2 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 032	Room B2 fountain	Yes	0.007		Removed	
FX 033	Room B3 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 034	Room B3 fountain	Yes	0.018	Immediately removed from service		
FX 035	Room B4 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 036	Room B4 fountain	Yes	0.010		Removed	
FX 037	Room B5 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 038	Room B5 fountain	Yes	0.005		Removed	
FX 039	Room B6 sink	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 040		No				
FX 041		No				
FX 042	NE Hall low fountain	Yes	0.0009			No action required
FX 043	NE Hall high fountain	Yes	0.0009			No action required
FX 044		No				
FX 045		No				
FX 046	Nurse office sink	Yes	0.0009			No action required
FX 047		No				
FX 048		No				
FX 049		No				
FX 050		No				
FX 051		No				
FX 052		No				
FX 053		No				
FX 054	Fountain SE Hall high	Yes	0.003			No action required
FX 055	Bottle filler SE Hall	Yes	0.004			No action required
FX 056	Fountain SE Hall low	Yes	0.002			Re-tested after adding filter 1/13/2022; No further action required
FX 057		No				
FX 058	Fountain SW Hall low	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required
FX 059	Fountain SW Hall high	Yes	0.0009			Re-tested after adding filter 1/13/2022; No further action required

Lead Sample Test Results and Actions

SUNNYSIDE ELEMENTARY SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ($\mu\text{g/L}$) – fixture must be immediately removed from service	Bin 2 - Lead concentrations greater than 5.0 $\mu\text{g/L}$ less than 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 060		No				
FX 061		No				
FX 062		No				
FX 063		No				
FX 064		No				
FX 065	NW Hall H fountain	Yes	0.0009			No action required
FX 066	NW Hall L fountain	Yes	0.0009			No action required
FX 067	NW Hall bottle filler	Yes	0.0009			No action required
FX 068		No				
FX 069	Kitchen sink	Yes	0.001			No action required
FX 070	Kitchen sink sprayer	Yes	0.001			No action required