

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 $\mu\text{g/L}$ to 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 001		No				
FX 002		No				
FX 003		No				
FX 004		No				
FX 005	Hub fountain	Yes	0.0009			No action required
FX 006	Hub fountain	Yes	0.0009			No action required
FX 007		No				
FX 008		No				
FX 009		No				
FX 010		No				
FX 011		No				
FX 012		No				
FX 013		No				
FX 014		No				
FX 015		No				
FX 016		No				
FX 017		No				
FX 018		No				
FX 019	Hub coffee shop	Yes	0.0009			No action required
FX 020	Hub coffee shop	Yes	0.0009			No action required
FX 021		No				
FX 022		No				
FX 023		No				
FX 024		No				
FX 025		No				
FX 026	Hub kitchen	Yes	0.0009			No action required
FX 027		No				
FX 028	Hub kitchen	Yes	0.001			No action required
FX 029		No				
FX 030	Hub kitchen	Yes	0.0009			No action required
FX 031		No				
FX 032	Hub kitchen	Yes	0.0009			No action required
FX 033		No				
FX 034	Hub kitchen	Yes	0.0009			No action required
FX 035		No				
FX 036		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 $\mu\text{g/L}$ to 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 037		No				
FX 038		No				
FX 039		No				
FX 040		No				
FX 041		No				
FX 042	Hub rm 118	Yes	0.0009			No action required
FX 043		No				
FX 044	Hub rm 118	Yes	0.0009			No action required
FX 045		No				
FX 046	Hub rm 118	Yes	0.0009			No action required
FX 047		No				
FX 048		No				
FX 049	Lower Hub fountain	Yes	0.0009			No action required
FX 050	Lower Hub fountain	Yes	0.0009			No action required
FX 051		No				
FX 052		No				
FX 053		No				
FX 054		No				
FX 055		No				
FX 056		No				
FX 057		No				
FX 058		No				
FX 059		No				
FX 060		No				
FX 061		No				
FX 062		No				
FX 063		No				
FX 064		No				
FX 065		No				
FX 066		No				
FX 067		No				
FX 068		No				
FX 069		No				
FX 070		No				
FX 071		No				
FX 072		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 073	SC 103 fountain	Yes	0.0009			No action required
FX 074	SC rm 105 sink	Yes	0.006		Must be fixed, replaced or removed	
FX 075		No				
FX 076		No				
FX 077		No				
FX 078	SC rm 107 sink	Yes	0.0009			No action required
FX 079		No				
FX 080	Fountain S14	Yes	0.009		Must be fixed, replaced or removed	
FX 081	SC rm 110 sink	Yes	0.0009			No action required
FX 082		No				
FX 083		No				
FX 084		No				
FX 085		No				
FX 086		No				
FX 087		No				
FX 088		No				
FX 089		No				
FX 090		No				
FX 091		No				
FX 092		No				
FX 093	FH pool fountain	Yes	0.0009			No action required
FX 094		No				
FX 095		No				
FX 096		No				
FX 097		No				
FX 098		No				
FX 099		No				
FX 100		No				
FX 101		No				
FX 102		No				
FX 103		No				
FX 104		No				
FX 105		No				
FX 106		No				
FX 107		No				
FX 108		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 109		No				
FX 110		No				
FX 111		No				
FX 112		No				
FX 113		No				
FX 114		No				
FX 115		No				
FX 116		No				
FX 117		No				
FX 118		No				
FX 119		No				
FX 120		No				
FX 121		No				
FX 122		No				
FX 123		No				
FX 124		No				
FX 125		No				
FX 126		No				
FX 127		No				
FX 128		No				
FX 129		No				
FX 130		No				
FX 131		No				
FX 132		No				
FX 133		No				
FX 134		No				
FX 135		No				
FX 136		No				
FX 137		No				
FX 138		No				
FX 139		No				
FX 140		No				
FX 141		No				
FX 142		No				
FX 143		No				
FX 144		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 $\mu\text{g/L}$ to 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 145		No				
FX 146		No				
FX 147		No				
FX 148		No				
FX 149		No				
FX 150		No				
FX 151		No				
FX 152		No				
FX 153		No				
FX 154		No				
FX 155		No				
FX 156		No				
FX 157		No				
FX 158		No				
FX 159		No				
FX 160		No				
FX 161		No				
FX 162		No				
FX 163		No				
FX 164		No				
FX 165		No				
FX 166		No				
FX 167		No				
FX 168		No				
FX 169		No				
FX 170		No				
FX 171		No				
FX 172		No				
FX 173		No				
FX 174		No				
FX 175		No				
FX 176		No				
FX 177		No				
FX 178		No				
FX 179		No				
FX 180		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 181		No				
FX 182		No				
FX 183		No				
FX 184		No				
FX 185		No				
FX 186	FH boys LR fountain	Yes	0.008		Must be fixed, replaced or removed	
FX 187		No				
FX 188		No				
FX 189		No				
FX 190		No				
FX 191		No				
FX 192	SC rm 201 sink	Yes	0.0009			No action required
FX 193		No				
FX 194		No				
FX 195		No				
FX 196	SC rm 202 sink	Yes	0.0009			No action required
FX 197		No				
FX 198	SC 2/F hall font.	Yes	0.0009			No action required
FX 199		No				
FX 200		No				
FX 201		No				
FX 202		No				
FX 203		No				
FX 204		No				
FX 205		No				
FX 206		No				
FX 207		No				
FX 208		No				
FX 209		No				
FX 210		No				
FX 211		No				
FX 212		No				
FX 213	FH fountain	Yes	0.0009			No action required
FX 214	FH fountain	Yes	0.001			No action required
FX 215		No				
FX 216		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 217		No				
FX 218		No				
FX 219		No				
FX 220	FH fountain N gym	Yes	0.0009			No action required
FX 221	FH fountain N gym	Yes	0.0009			No action required
FX 222		No				
FX 223	S. concessions sink	Yes	0.001			No action required
FX 224		No				
FX 225		No				
FX 226		No				
FX 227		No				
FX 228	FH gym S. fountain	Yes	0.0009			No action required
FX 229		No				
FX 230		No				
FX 231		No				
FX 232		No				
FX 233		No				
FX 234		No				
FX 235		No				
FX 236		No				
FX 237		No				
FX 238		No				
FX 239		No				
FX 240		No				
FX 241		No				
FX 242		No				
FX 243		No				
FX 244		No				
FX 245		No				
FX 246		No				
FX 247		No				
FX 248		No				
FX 249		No				
FX 250		No				
FX 251		No				
FX 252	Fountain by 110 MC	Yes	0.0009			No action required

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 253		No				
FX 254		No				
FX 255		No				
FX 256	Fountain 1/F MC	Yes	0.0009			No action required
FX 257	Fountain 1/F MC	Yes	0.0009			No action required
FX 258		No				
FX 259		No				
FX 260		No				
FX 261		No				
FX 262		No				
FX 263		No				
FX 264		No				
FX 265		No				
FX 266		No				
FX 267		No				
FX 268	Fountain 1/F MC	Yes	0.0009			No action required
FX 269		No				
FX 270		No				
FX 271	Fountain 1/F ramp	Yes	0.0009			No action required
FX 272	Sink room 104A MC	Yes	0.0009			No action required
FX 273		No				
FX 274	Sink room 104A MC	Yes	0.0009			No action required
FX 275		No				
FX 276	Sink room 104A MC	Yes	0.004			No action required
FX 277		No				
FX 278	Sink room 104A MC	Yes	0.001			No action required
FX 279		No				
FX 280		No				
FX 281		No				
FX 282		No				
FX 283		No				
FX 284		No				
FX 285		No				
FX 286		No				
FX 287		No				
FX 288		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 $\mu\text{g/L}$ to 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 289		No				
FX 290		No				
FX 291		No				
FX 292	Fountain old gym	Yes	0.0009			No action required
FX 293	Fountain old gym	Yes	0.0009			No action required
FX 294		No				
FX 295		No				
FX 296		No				
FX 297		No				
FX 298		No				
FX 299		No				
FX 300		No				
FX 301		No				
FX 302		No				
FX 303		No				
FX 304		No				
FX 305		No				
FX 306		No				
FX 307		No				
FX 308		No				
FX 309		No				
FX 310		No				
FX 311		No				
FX 312		No				
FX 313		No				
FX 314		No				
FX 315		No				
FX 316		No				
FX 317		No				
FX 318		No				
FX 319		No				
FX 320		No				
FX 321		No				
FX 322		No				
FX 323		No				
FX 324		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 325		No				
FX 326		No				
FX 327		No				
FX 328		No				
FX 329		No				
FX 330		No				
FX 331		No				
FX 332		No				
FX 333		No				
FX 334		No				
FX 335		No				
FX 336		No				
FX 337		No				
FX 338		No				
FX 339		No				
FX 340		No				
FX 341		No				
FX 342		No				
FX 343		No				
FX 344	Sink engineer breaker	Yes	0.0009			No action required
FX 345		No				
FX 346		No				
FX 347		No				
FX 348		No				
FX 349		No				
FX 350	Fountain girls LR OG	Yes	0.032	Must be immediately removed		
FX 351	Fountain girls LR OG	Yes	0.042	Must be immediately removed		
FX 352		No				
FX 353		No				
FX 354		No				
FX 355		No				
FX 356		No				
FX 357		No				
FX 358		No				
FX 359		No				
FX 360		No				

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 361		No				
FX 362		No				
FX 363		No				
FX 364		No				
FX 365		No				
FX 366		No				
FX 367		No				
FX 368		No				
FX 369		No				
FX 370		No				
FX 371	Fountain 2/F MC	Yes	0.0009			No action required
FX 372	Fountain 2/F MC	Yes	0.0009			No action required
FX 373		No				
FX 374		No				
FX 375		No				
FX 376		No				
FX 377		No				
FX 378		No				
FX 379	Sink care room MC	Yes	0.005		Must be fixed, replaced or removed	
FX 380		No				
FX 381		No				
FX 382		No				
FX 383		No				
FX 384		No				
FX 385		No				
FX 386	Fountain 2/F MC	Yes	0.0009			No action required
FX 387		No				
FX 388	Fountain Choir hall	Yes	0.0009			No action required
FX 389		No				
FX 390		No				
FX 391		No				
FX 392		No				
FX 393		No				
FX 394	Sink room 209D	Yes	0.064	Must be immediately removed		
FX 395		No				
FX 396	Sink room 209E	Yes	0.001			No action required

# Lead Sample Test Results and Actions

## GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter (µg/L) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 µg/L to 15.0 µg/L – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 µg/L – no action is required.
FX 397		No				
FX 398	Fountain 3/F MC	Yes	0.0009			No action required
FX 399		No				
FX 400		No				
FX 401		No				
FX 402		No				
FX 403		No				
FX 404		No				
FX 405		No				
FX 406	Sink room 307 MC	Yes	0.0009			No action required
FX 407		No				
FX 408	Sink room 302	Yes	0.004			No action required
FX 409	SC rm 306 MC	Yes	0.006		Must be fixed, replaced or removed	
FX 410		No				
FX 411		No				
FX 412	SC rm 306 MC	Yes	0.002			No action required
FX 413		No				
FX 414		No				
FX 415		No				
FX 416	Sink rm 304A MC	Yes	0.002			No action required
FX 417		No				
FX 418		No				
FX 419		No				
FX 420	Sink rm 304A MC	Yes	0.002			No action required
FX 421		No				
FX 422	Sink rm 304A MC	Yes	0.006		Must be fixed, replaced or removed	
FX 423		No				
FX 424	Sink rm 304A MC	Yes	0.008		Must be fixed, replaced or removed	
FX 425		No				
FX 426		No				
FX 427		No				
FX 428		No				
FX 429		No				
FX 430		No				
FX 431		No				
FX 432		No				

## Lead Sample Test Results and Actions

### GREAT FALLS HIGH SCHOOL

Fixture Number	Location	Part of Sampling Plan	Sampling Results (ppm)	Bin 1 - Lead concentrations greater than 15.0 micrograms per Liter ( $\mu\text{g/L}$ ) – fixture must be immediately removed from service	Bin 2 - Lead concentrations equal or greater than 5.0 $\mu\text{g/L}$ to 15.0 $\mu\text{g/L}$ – fixture must be fixed, replaced or removed from service	Bin 3 - Lead concentrations less than 5.0 $\mu\text{g/L}$ – no action is required.
FX 433		No				
FX 434		No				
FX 435		No				
FX 436		No				
FX 437	Sink rm 304 MC	Yes	0.013		Must be fixed, replaced or removed	
FX 438	Sink rm 305 MC	Yes	0.012		Must be fixed, replaced or removed	
FX 439		No				
FX 440	Sink rm 305 MC	Yes	0.007		Must be fixed, replaced or removed	
FX 441		No				
FX 442		No				
FX 443		No				
FX 444	Sink rm 305A MC	Yes	0.003			No action required